

## SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

	A	B	C	D	E
1	Site:	Webster Elementary School	Date:	10/20/17	
2	Sampler:	SDUSD - Safety Office	Analyzed By:	EnvioMatrix Analytical, Inc	
3	Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB. Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level				
4					
5					
6					
7	Sample ID	Sample Location	Lead Results	Units	Type of Fixture
8	1	Admin Buldg Exterior S- Wall, L-Side	6.03	ug/L	DB
9	2	Admin Bldg Exterior S-Wall, R-Side	2.76	ug/L	DB
10	3	Room 1 S/E corner	2.69	ug/L	DB
11	4	Room 2 N/E corner	1.67	ug/L	DB
12	5	Room 3 N/ E corner	3.79	ug/L	DB
13	6	Room 4 N/W corner	3.94	ug/L	DB
14	7	Room 5 S/W corner-water turned off-Tagged	n/a		
15	8	Kitchen S/E corner	4.81	ug/L	KF
16	9	Lunch court, west wall, left side, OUT OF SERVICE	n/a		
17	10	Lunch court, west wall, right side, OUT OF SERVICE	n/a		
18	11	Room 6 N-Wall	17.7	ug/L	DB
19	12	Room 7 - N-Wall	3.72	ug/L	DB
20	13	Room 8 - N- Wall	2.09	ug/L	DB
21	14	Room 9 - N-Wall	4.83	ug/L	DB
22	15	Classroom Bldg 6-9, Outside W-Wall L-Side	3.96	ug/L	DB
23	16	Classroom Bldge 6 - 9, Outside W-Wall R-Side	3.70	ug/L	DB
24	17	B-1 E-Wall	6.84	ug/L	DB
25	18	B-2 E-Wall	8.66	ug/L	DB
26	19	B-3 E-Wall	4.43	ug/L	DB
27	20	Bungalow B-4/West Wall	7.12	ug/L	DB
28	21	Bungalow B-5/West Wall	15	ug/L	DB
29	22	Bungalow B-6/East Wall	7.57	ug/L	DB
30	23	Bungalow B-7/East Wall	26.1	ug/L	DB
31	24	Bungalow B-8/East Wall	11.8	ug/L	DB
32	25	Exterior B4, Bubbler-Left Bank/Left - <b>Out of Service</b>	n/a		
33	26	Exterior B4, Bubbler-Left Bank/Cntr - <b>Out of Service</b>	n/a		
34	27	Exterior B4, Bubbler-Left Bank/right - <b>Out of Service</b>	n/a		

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet

# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

	A	B	C	D	E
35	Site:	Webster Elementary School	Date:	10/20/17	
36	Sampler:	SDUSD - Safety Office	Analyzed By:	EnvioMatrix Analytical, Inc	
37	<b>Sample ID</b>	<b>Sample Location</b>	<b>Lead Results</b>	<b>Units</b>	<b>Type of Fixture</b>
38	<p>Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.                      Green shading = below District &amp; Federal Action Levels                      Yellow shading = below Federal Action level/Above District Action Level</p>				
39					
40					
41					
42	28	Exterior B4, Bubbler-right Bank/Left - <b>Out of Service</b>	n/a		
43	29	Exterior B4, Bubbler-right Bank/cntr - <b>Out of Service</b>	n/a		
44	30	Exterior B4, Bubbler-right Bank/right - <b>Out of Service</b>	n/a		
45	31	B-9, W-Wall	9.31	ug/L	DB
46	32	B-10, W-Wall	5.72	ug/L	DB
47	33	Room 10 Kinder-Island trough bubbler	3.63	ug/L	DB
48	34	Room 11 - Island - trough bubbler	3.13	ug/L	DB
49	35	Exterior Room 10/11, S- Wall, L-Side	2.75	ug/L	DB
50	36	Exterior Room 10/11, S-Wall, R-Side	1.94	ug/L	DB
51	37	2 - Story Room 12, W-Wall bubbler	0.84	ug/L	DB
52	38	2 Story Room 13, W Wall bubbler - <b>Valve Closed</b>	n/a		
53	39	2 Story Room 15, - S-Wall bubbler	1.72	ug/L	DB
54	40	2 Story Room 16, E - Wall bubbler	0.92	ug/L	DB
55	41	2 Story Room 17, W-Wall bubbler	0.33	ug/L	DB
56	42	2-Story Room 18, W-Wall bubbler	0.32	ug/L	DB
57	43	2-Story Room 19, S-Wall bubbler	0.32	ug/L	DB
58	44	2-Story Room 20, S-Wall bubbler	1.14	ug/L	DB
59	45	2-Story Room 21, S-Wall bubbler	0.32	ug/L	DB
60	46	Library Ext. W-Wall facing Room 16, L-Side	1.38	ug/L	DB
61	<b>2017 City Water Department Sampling Results</b>				
62	1	admin, nurses office goose neck faucet	<5	ug/L	NS
63	2	Café, East facing wall, cntr bubbler	7.14	ug/L	DB
64	3	Bldg w/rms 6-9, west wall, B & G RR, far right bubbler	<5	ug/L	DB
65	4	Bungalos, E. facing, left triple fountain, far left bubbler	5.09	ug/L	DB
66	5	Library, W. facing, drinking fountains, right bubbler	<5	ug/L	DB

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet