

# SDUSD-Safety Office Sampling Log

Site: Baypoint ECE

2-Oct-17

Sampler SDUSD-Safety Office

Enviromatrix Labs: 17I0659 Baypoint ECE

Sample ID		Description		Lead	Units	Comments
1		Storeroom		0.64	ug/l	next to girl's restroom
2		Room 1		0.79	ug/l	bubbler
3		Room 2		0.79	ug/l	bubbler
4		Room 3		0.88	ug/l	bubbler
5		Kitchen		1.69	ug/l	faucet