

October 09, 2018

Irene Hightower  
Principal  
Cabrillo Elementary  
7375 Wheatley St.  
San Diego, CA 92111

Subject: Cabrillo Elementary Drinking Water Project Closeout

Dear Irene Hightower

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Cabrillo Elementary campus.

As part of a district wide effort the Safety Office began testing all drinking water outlets at Cabrillo Elementary for elevated levels of lead. Safety Office staff first identified all drinking water outlets and tagged them with a blue sticker. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to an accredited local laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Cabrillo Elementary campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto  
Manager, Facilities Planning



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Cabrillo

Report Type: Close Out Report

Date of Report: 10/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 3 Admin - Cabrillo_03-03 Nurse Health, South Wall	DWO-041-001	Faucet	4.92	INIT	
2 7 Kinder Rms K01-K02 - Cabrillo_07-07 Building Exterior, East Wall	DWO-041-002	Drinking Fountain Bubblers	<5	INIT	
3 7 Kinder Rms K01-K02 - Cabrillo_07-07 Classroom - K01, North Wall	DWO-041-003	Drinking Fountain Bubblers	8.82	FLTR	ND
4 7 Kinder Rms K01-K02 - Cabrillo_07-07 Classroom - K02, South Wall	DWO-041-004	Drinking Fountain Bubblers	5.14	FLTR	ND
5 7 Kinder Rms K01-K02 - Cabrillo_07-07 Classroom - K02, South Wall	DWO-041-005	Drinking Fountain Bubblers	5.55	FLTR	
6 Portable B06 - Cabrillo Classroom - B06, West Wall	DWO-041-006	Drinking Fountain Bubblers	<5	INIT	
7 Portable B02 - Cabrillo Building Exterior, North Wall Left Side	DWO-041-007	Drinking Fountain Bubblers	14.91	FLTR	ND
8 Portable B02 - Cabrillo Building Exterior, North Wall Middle	DWO-041-008	Drinking Fountain Bubblers	6.51	FLTR	0.162
9 Portable B02 - Cabrillo Building Exterior, North Wall Right Side	DWO-041-009	Drinking Fountain Bubblers	7.29	FLTR	ND
10 Portable B02 - Cabrillo Classroom - B02, South Wall	DWO-041-010	Drinking Fountain Bubblers	9.80	FLTR	ND
11 Portable B01 - Cabrillo Classroom - B01, South Wall	DWO-041-011	Drinking Fountain Bubblers	6.68	FLTR	0.197
12 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Hallway by Auditorium, North Wall	DWO-041-012	Drinking Fountain Bubblers	8.41	RMOV	
13 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Hallway by Auditorium, North Wall	DWO-041-013	Drinking Fountain Bubblers	4.07	RMOV	
14 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Dining Rm Faculty, East Wall	DWO-041-014	Faucet	15.35	FLTR	0.216
15 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Kitchen, South Wall	DWO-041-015	Faucet	4.26	INIT	
16 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Classroom - 14, West Wall	DWO-041-016	Drinking Fountain Bubblers	6.43	FLTR	0.314
17 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Classroom - 12, East Wall	DWO-041-017	Drinking Fountain Bubblers	6.87	FLTR	0.251



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Cabrillo

Report Type: Close Out Report

Date of Report: 10/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Classroom - 11, West Wall	DWO-041-018	Drinking Fountain Bubler	4.51	INIT	
19 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Classroom - 10, East Wall	DWO-041-019	Drinking Fountain Bubler	6.73	FLTR	0.166
20 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Building Exterior, North Wall Left Side	DWO-041-020	Drinking Fountain Bubler	31.40	FLTR	ND
21 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Building Exterior, North Wall Right Side	DWO-041-021	Drinking Fountain Bubler	<5	INT	
22 6 Classrooms B15-B18 - Cabrillo_06-06 Classroom - 15, West Wall	DWO-041-022	Drinking Fountain Bubler	8.69	FLTR	
23 6 Classrooms B15-B18 - Cabrillo_06-06 Classroom - 16, East Wall	DWO-041-023	Drinking Fountain Bubler	15.32	FLTR	ND
24 6 Classrooms B15-B18 - Cabrillo_06-06 Classroom - 17, West Wall	DWO-041-024	Drinking Fountain Bubler	NA	RMOV	
25 6 Classrooms B15-B18 - Cabrillo_06-06 Classroom - 18, East Wall	DWO-041-025	Drinking Fountain Bubler	12.74	FLTR	ND
26 8 Library - Cabrillo_08-08 Workroom, West Wall	DWO-041-026	Faucet	ND	INIT	
27 Portable B05 - Cabrillo Classroom - B05, North Wall	DWO-041-027	Drinking Fountain Bubler	5.91	FLTR	0.242
28 Portable B04 - Cabrillo Classroom - B04, North Wall	DWO-041-028	Drinking Fountain Bubler	5.59	FLTR	0.269
29 Portable B03 - Cabrillo Classroom - B03, West Wall	DWO-041-029	Drinking Fountain Bubler	<5	INIT	
30 5 Auditorium/Cafeteria/Kitchen/Rms 10-14 - Cabrillo_05-05 Kitchen, East Wall	DWO-041-030	Faucet	4.95	INIT	

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Cabrillo

Report Type: Close Out Report

Date of Report: 10/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------

**\*\*Clearance actions**

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.