

January 15, 2019

Hernan Baeza  
Principal  
Kimbrough Elementary School  
321 Hoitt St.  
San Diego, CA 92102

Subject: Kimbrough School Drinking Water Project Closeout

Dear Hernan Baeza:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Kimbrough ES campus.

As part of a district wide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Kimbrough ES for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Kimbrough ES campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto  
Manager, Facilities Planning



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Left	DWO-162-001	Faucet	2.57	INIT	
2	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Center Left	DWO-162-002	Faucet	ND	INIT	
3	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Center Right	DWO-162-003	Drinking Fountain Bubblers	<5	INIT	
4	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Right	DWO-162-004	Drinking Fountain Bubblers	ND	INIT	
5	3 Admin/Supply - Kimbrough_01-03 Nurse Health, North Wall	DWO-162-005	Drinking Fountain Bubblers	ND	INIT	
6	3 Admin/Supply - Kimbrough_01-03 Lounge, East Wall	DWO-162-006	Drinking Fountain Bubblers	ND	INIT	
7	3 Admin/Supply - Kimbrough_01-03 Community Rm, East Wall	DWO-162-007	Faucet	3.76	INIT	
8	Portable B02 - Kimbrough Workshop, East Wall	DWO-162-008	Faucet	<5	INIT	
9	Portable B04 - Kimbrough Classroom - B04 Multi-Purpose, East Wall	DWO-162-009	Drinking Fountain Bubblers	ND	INIT	
10	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 101, West Wall	DWO-162-010	Drinking Fountain Bubblers	ND	INIT	
11	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 102, West Wall	DWO-162-011	Faucet	3.57	INIT	
12	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 103, West Wall	DWO-162-012	Drinking Fountain Bubblers	ND	INIT	
13	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 104, West Wall	DWO-162-013	Drinking Fountain Bubblers	ND	INIT	
14	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 105, East Wall	DWO-162-014	Faucet	4.53	INIT	
15	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 105, West Wall	DWO-162-015	Drinking Fountain Bubblers	ND	INIT	
16	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 106, East Wall	DWO-162-016	Drinking Fountain Bubblers	ND	INIT	
17	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 107, Westwall	DWO-162-017	Drinking Fountain Bubblers	ND	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 108, West Wall	DWO-162-018	Faucet	2.96	INIT	
19	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 108, West Wall	DWO-162-019	Drinking Fountain Bubblers	ND	INIT	
20	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 110, East Wall	DWO-162-020	Drinking Fountain Bubblers	3.05	INIT	
21	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 111, East Wall	DWO-162-021	Drinking Fountain Bubblers	ND	INIT	
22	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 112, West Wall	DWO-162-022	Drinking Fountain Bubblers	2.61	INIT	
23	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 113, West Wall	DWO-162-023	Drinking Fountain Bubblers	ND	INIT	
24	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 201, East Wall	DWO-162-024	Drinking Fountain Bubblers	<5	INIT	
25	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 202, East Wall	DWO-162-025	Drinking Fountain Bubblers	ND	INIT	
26	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 202, South Wall	DWO-162-026	Drinking Fountain Bubblers	ND	INIT	
27	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 203, East Wall	DWO-162-027	Drinking Fountain Bubblers	ND	INIT	
28	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 204, East Wall	DWO-162-028	Drinking Fountain Bubblers	ND	INIT	
29	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 205, East Wall	DWO-162-029	Drinking Fountain Bubblers	ND	INIT	
30	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 206, East Wall	DWO-162-030	Drinking Fountain Bubblers	ND	INIT	
31	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 208, East Wall	DWO-162-031	Drinking Fountain Bubblers	ND	INIT	
32	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 208, East Wall	DWO-162-032	Drinking Fountain Bubblers	<5	INIT	
33	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 209, East Wall	DWO-162-033	Drinking Fountain Bubblers	ND	INIT	
34	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 210, Southeast Right	DWO-162-034	Drinking Fountain Bubblers	ND	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 211, West Wall	DWO-162-035	Drinking Fountain Bubblers	ND	INIT	
36	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 212, East Wall	DWO-162-036	Drinking Fountain Bubblers	ND	INIT	
37	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 213, East Wall	DWO-162-037	Drinking Fountain Bubblers	ND	INIT	
38	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 213, West Wall	DWO-162-038	Drinking Fountain Bubblers	ND	INIT	
39	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Right	DWO-162-039	Drinking Fountain Bubblers	ND	INIT	
40	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Left	DWO-162-040	Drinking Fountain Bubblers	ND	INIT	
41	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Left	DWO-162-041	Drinking Fountain Bubblers	ND	INIT	
42	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Left	DWO-162-042	Drinking Fountain Bubblers	ND	INIT	
43	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Right	DWO-162-043	Drinking Fountain Bubblers	ND	INIT	
44	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Right	DWO-162-044	Drinking Fountain Bubblers	ND	INIT	
45	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Right	DWO-162-045	Drinking Fountain Bubblers	ND	INIT	
46	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Center Right	DWO-162-046	Drinking Fountain Bubblers	ND	INIT	
47	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Center Right	DWO-162-047	Faucet	ND	INIT	
48	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Left Center	DWO-162-048	Drinking Fountain Bubblers	ND	INIT	
49	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Left	DWO-162-049	Drinking Fountain Bubblers	ND	INIT	
50	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Left	DWO-162-050	Drinking Fountain Bubblers	ND	INIT	
51	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center Left	DWO-162-051	Drinking Fountain Bubblers	ND	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
52	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center	DWO-162-052	Drinking Fountain Bubblers	ND	INIT	
53	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center Right	DWO-162-053	Drinking Fountain Bubblers	ND	INIT	
54	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Right	DWO-162-054	Drinking Fountain Bubblers	ND	INIT	
55	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Left	DWO-162-055	Drinking Fountain Bubblers	ND	INIT	
56	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Left	DWO-162-056	Drinking Fountain Bubblers	ND	INIT	
57	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Left	DWO-162-057	Drinking Fountain Bubblers	ND	INIT	
58	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Right	DWO-162-058	Faucet	ND	INIT	
59	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 101/102, South Wall	DWO-162-059	Drinking Fountain Bubblers	ND	INIT	
60	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 104-107, South Wall	DWO-162-060	Drinking Fountain Bubblers	5.05	PLMB	4.06
61	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 109-112, South Wall	DWO-162-061	Drinking Fountain Bubblers	2.82	INIT	
62	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 204-207, East Wall	DWO-162-062	Drinking Fountain Bubblers	2.82	INIT	
63	4 Kitchen/Multi-Purpose - Kimbrough_01-04 Kitchen, North Wall	DWO-162-063	Drinking Fountain Bubblers	3.04	INIT	
64	Portables 114/214 - Kimbrough Classroom - 114, South Wall	DWO-162-064	Drinking Fountain Bubblers	ND	INIT	
65	Portables 114/214 - Kimbrough Classroom - 214, South Wall	DWO-162-065	Drinking Fountain Bubblers	ND	INIT	
66	Portables 115/215 - Kimbrough Classroom - 115, South Wall	DWO-162-066	Drinking Fountain Bubblers	3.84	INIT	
67	Portables 115/215 - Kimbrough Classroom - 215, South Wall	DWO-162-067	Drinking Fountain Bubblers	ND	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
68 Portables 116/216 - Kimbrough Classroom - 116, North Wall	DWO-162-068	Drinking Fountain Bubblers	ND	INIT	
69 Portables 116/216 - Kimbrough Classroom - 116, North Wall	DWO-162-069	Drinking Fountain Bubblers	19.39	FLTR	ND
70 Portables 116/216 - Kimbrough Classroom - 216, North Wall	DWO-162-070	Drinking Fountain Bubblers	2.76	INIT	
71 Portables 117/217 - Kimbrough Classroom - 217, East Wall	DWO-162-071	Drinking Fountain Bubblers	ND	INIT	
72 1 Kinder Rms K03-K05 - Kimbrough_01-01 Building Exterior, East Wall Left	DWO-162-072	Drinking Fountain Bubblers	7.29	FLTR	ND
73 1 Kinder Rms K03-K05 - Kimbrough_01-01 Building Exterior, East Wall Right	DWO-162-073	Drinking Fountain Bubblers	ND	INIT	
74 1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K03, East Wall	DWO-162-074	Faucet	3.76	INIT	
75 1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K04, East Wall	DWO-162-075	Faucet	2.52	INIT	
76 1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Right	DWO-162-076	Faucet	2.81	INIT	
77 1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Left	DWO-162-077	Drinking Fountain Bubblers	2.74	INIT	
78 1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Right Sink	DWO-162-078	Drinking Fountain Bubblers	ND	INIT	
79 Portables 118/218 - Kimbrough Classroom - 118, West Wall	DWO-162-079	Drinking Fountain Bubblers	ND	INIT	
80 Portables 118/218 - Kimbrough Classroom - 118, East Wall	DWO-162-080	Drinking Fountain Bubblers	ND	INIT	
81 Portables 118/218 - Kimbrough Classroom - 218, West Wall	DWO-162-081	Drinking Fountain Bubblers	2.94	INIT	
82 Portables 119/219 - Kimbrough Classroom - 119, East Wall	DWO-162-083	Drinking Fountain Bubblers	2.98	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Close Out Report

Date of Report: 1/15/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
83 Portables 119/219 - Kimbrough Classroom - 219, East Wall	DWO-162-084	Faucet	ND	INIT	
84 2 Kinder Rms K01-K02/Learning Center - Kimbrough Counseling Center, North Wall	DWO-162-085	Faucet	ND	INIT	
85 2 Kinder Rms K01-K02/Learning Center - Kimbrough Counseling Center, West Wall	DWO-162-091	Faucet	ND	INIT	
86 2 Kinder Rms K01-K02/Learning Center - Kimbrough Workroom in Library, South Wall	DWO-162-092	Faucet	ND	INIT	
87 6 Restrooms - Kimbrough_01-06 Building Exterior, West Wall Left	DWO-162-093	Faucet	ND	INIT	
88 6 Restrooms - Kimbrough_01-06 Building Exterior, West Wall Right	DWO-162-094	Faucet	ND	INIT	

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.