

May 14, 2019

Courtney Browne
Principal
Mt. Everest Academy
4350 Mt Everest Blvd
San Diego, CA 92117

Subject: Mt. Everest Academy Drinking Water Project Closeout

Dear Mrs. Browne:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Mt. Everest Academy campus.

As part of a Districtwide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Mt. Everest Academy for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Mt. Everest Academy campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto
Manager, Facilities Planning



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Mt. Everest Academy

Report Type: Closeout Report

Date of Report: 5/14/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 3 Admin - Mt. Everest_01-03 Workroom, West Wall	DWO-299-001	Faucet	2.08		
2 3 Admin - Mt. Everest_01-03 Lounge, North Wall	DWO-299-002	Faucet	1.97		
3 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 01, West Wall	DWO-299-003	Drinking Fountain Bubblers	7.30	FLTR	ND
4 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 02, East Wall	DWO-299-004	Drinking Fountain Bubblers	4.84		
5 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 03, West Wall	DWO-299-007	Drinking Fountain Bubblers	5.91	FLTR	ND
6 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 06, West Wall	DWO-299-008	Drinking Fountain Bubblers	2.71		
7 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 05, East Wall	DWO-299-009	Drinking Fountain Bubblers	6.81	FLTR	ND
8 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Classroom - 04, West Wall	DWO-299-010	Drinking Fountain Bubblers	4.82		
9 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Building Exterior, West Wall	DWO-299-011	Drinking Fountain Bubblers	<5		
10 4 Classrooms 1-6/Supply - Mt. Everest_01-04 Building Exterior, West Wall	DWO-299-012	Drinking Fountain Bubblers	2.42		
11 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 07, West Wall	DWO-299-013	Drinking Fountain Bubblers	<5		
12 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 08, East Wall	DWO-299-014	Drinking Fountain Bubblers	10.30	FLTR	ND
13 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 09, West Wall	DWO-299-015	Drinking Fountain Bubblers	5.39	FLTR	ND
14 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 12, West Wall	DWO-299-016	Drinking Fountain Bubblers	6.34	FLTR	ND
15 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 11, East Wall	DWO-299-017	Drinking Fountain Bubblers	4.94		
16 5 Classrooms 7-12 - Mt. Everest_01-05 Classroom - 10, West Wall	DWO-299-018	Drinking Fountain Bubblers	5.90	FLTR	ND



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Mt. Everest Academy

Report Type: Closeout Report

Date of Report: 5/14/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	5 Classrooms 7-12 - Mt. Everest_01-05 Building Exterior, West Wall	DWO-299-020	Drinking Fountain Bubblers	<5		
18	5 Classrooms 7-12 - Mt. Everest_01-05 Building Exterior, West Wall	DWO-299-021	Drinking Fountain Bubblers	2.75		
19	Portable B06 - Mt. Everest Offices - B06, North Wall	DWO-299-022	Faucet	ND		
20	Portable B05 - Mt. Everest Offices - B05, East Wall	DWO-299-023	Faucet	1.32		
21	Portable B04 - Mt. Everest Offices - B04, East Wall	DWO-299-024	Faucet	1.06		
22	Portable B03 - Mt. Everest Offices - B03, East Wall	DWO-299-025	Faucet	ND		
23	Portable B02 - Mt. Everest Offices - B02, East Wall	DWO-299-026	Faucet	1.05		
24	Portable B01 - Mt. Everest Offices - B01, East Wall	DWO-299-027	Faucet	1.00		
25	1 Classrooms 13-14 - Mt. Everest_01-01 Classroom - 14 Eye & Otology, East Wall	DWO-299-028	Faucet	20.40	FLTR	ND
26	1 Classrooms 13-14 - Mt. Everest_01-01 Building Exterior, West Wall	DWO-299-029	Drinking Fountain Bubblers	5.03	FLTR	ND
27	1 Classrooms 13-14 - Mt. Everest_01-01 Building Exterior, West Wall	DWO-299-030	Drinking Fountain Bubblers	9.62	FLTR	ND
28	2 Auditorium/Cafeteria - Mt. Everest_01-02 Building Exterior, South Wall	DWO-299-031	Drinking Fountain Bubblers	<5		
29	2 Auditorium/Cafeteria - Mt. Everest_01-02 Building Exterior, South Wall	DWO-299-032	Drinking Fountain Bubblers	4.12		
30	2 Auditorium/Cafeteria - Mt. Everest_01-02 Science Prep, east Wall	DWO-299-033	Spray Faucet	1.32		
31	3 Admin - Mt. Everest_01-03 Assessment Rm 1, North Wall	DWO-299-034	Faucet	2.26		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Mt. Everest Academy

Report Type: Closeout Report

Date of Report: 5/14/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.