



May 22, 2018

Lori Sandoval  
Principal  
Wegeforth Elementary  
3443 Edihar Ave.  
San Diego, CA 92123

Subject: Wegeforth Elementary Drinking Water Project Closeout

Dear Lori:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Wegeforth Elementary campus.

On October 17, 2017, the district Safety Office sampled all drinking water outlets at Wegeforth Elementary for elevated levels of lead. Safety Office staff first identified all drinking water outlets and tagged them with a blue sticker. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to an accredited local laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Wegeforth Elementary campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Darin Vey  
Manager (TOC); Safety, Training, Personnel, & Environmental Compliance

# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Wegeforth Elementary School					Report Date:	05/17/18
Sampler:	SDUSD - Safety Office						
<b>Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.</b> Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level Units = ug/L							
Sample ID	Sample Location	Lead Results	Action Taken	Clearance Date	Clearance Result	Type of Fixture	
1	Main Building, Nurse's Office NW Side	2.96				NS	
2	Staff Lounge N-Wall Faucet	2.48				KF	
3	Outside Lunch Court, S-Wall, R-Side	2.40				DB	
4	Outside Lunch Court, S-Wall, L-Side	1.45				DB	
5	Outside Library, S-Wall, R-Side	2.28				DB	
6	Outside Library, S-Wall, L-Side	4.46				DB	
7	Library, inside small office-faucet	2.15				KF	
8	Room 1-SE corner	4.88				DB	
9	Room 2 - NE corner	5.26	R	2/1/2018	2.88	DB	
10	Room 3 - SE corner	6.05	R	2/1/2018	1.65	DB	
11	Room 4 - SW corner	2.50				DB	
12	Room 5 - NW corner	2.90				DB	
13	Room 6 - SW corner	3.06				DB	
14	Room 7, North East Wall, Bubblers	5.24	R	2/1/2018	2.32	DB	
15	Room 7, North East Wall, Faucet	3.28				CF	
16	Room 8, South East Wall, Bubblers	2.44				DB	
17	Room 9 , North East Wall, Bubblers	5.63	R	2/1/2018	2.15	DB	
18	Room 10, North West Wall, Bubblers	2.61				DB	
19	Room 11, South West Wall, Bubblers	8.82	F	3/21/2018	ND	DB	
20	N. Wall Building 7-10, Triple Bubblers, Middle Bubblers	1.96				DB	
21	N. Wall Building 7-10, Triple Bubblers, Far Left Bubblers	1.95				DB	
21.1	N. Wall Building 7-10, Triple Bubblers, Far Right Bubblers SD 3	< 5				DB	
22	Office 03, North West Wall, Bubblers	3.33				DB	
23	Kindergarten Building -Room k-2 West Wall, L-Side	2.17				DB	
24	Kindergarten Building -Room k-2 West Wall, R-Side	3.09				DB	

Coding: DB=Drinking Water Bubblers; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable;

F= Filter; R= Repaired; RM= Removed

SD 1 through SD 5 = Sampled by City of San Diego

# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Wegeforth Elementary School	Report Date:	05/16/18			
Sampler:	SDUSD - Safety Office					
<p><b>Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.</b></p> <p>Green shading = below District &amp; Federal Action Levels</p> <p>Yellow shading = below Federal Action level/Above District Action Level</p> <p>Red Shading = above Federal Action Level</p> <p>Units = ug/L</p>						
Sample ID	Sample Location	Lead Results	Action Taken	Clearance Date	Clearance Result	Type of Fixture
25	Kindergarten Building - Room k-1 -Island	1.37				DB
26	Bungalow-Room B2 - North Wall	0.88				DB
27	Bungalow-Room B3 - North Wall	1.24				DB
28	Bungalow-Room B4 - North Wall	1.27				DB
29	Bungalow-Room B5 - North Wall	20.1	F	2/1/2018	0.28	DB
30	Bldg. 300 Rm 302 NW Wall	Removed				
31	Kindergarten Building - Room k-2 -Island L	4.32				DB
32	Cafeteria West Wall 2 Comp Sink SD 1	5.85	R	2/1/2018	3.09	DB
33	Kindergarten Exterior R SD 2	6.12	F	3/21/2018	ND	DB
34	South Wall Rooms 1 - 6 R SD 4	5.16	F	3/21/2018	ND	DB
35	South Wall Rooms 1 - 6 L	Turned Off	F	3/21/2018	ND	DB
36	Kindergarten Building - Room k-2	3.27				DB
37	Kindergarten Building - Room k-2 -Island L	3.47				DB

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable;  
 F= Filter; R= Repaired; RM= Removed  
 SD 1 through SD 5 = Sampled by City of San Diego