



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/19/17

San Diego Unified School District  
**Audubon K-8**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165284	04/11/17	06:10 AM	SAMPLE 1	3710020-ADB-A	< 5	ug/L
W1165285	04/11/17	06:15 AM	SAMPLE 2	3710020-ADB-B	< 5	ug/L
W1165286	04/11/17	06:05 AM	SAMPLE 3	3710020-ADB-C	< 5	ug/L
W1165287	04/11/17	06:20 AM	SAMPLE 4	3710020-ADB-D	< 5	ug/L
W1165288	04/11/17	06:25 AM	SAMPLE 5	3710020-ADB-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	100s BLDG, Room 101, next to exit, bubbler in sink
SAMPLE 2	600s BLDG exterior, next to boys resroom, facing dirt field, triple fountain, right bubbler
SAMPLE 3	Assembly, exterior, between 219 and 220, dual fountain, upper right
SAMPLE 4	400's BLDG, exterior, near Room 409, two fountains, upper left single bubbler
SAMPLE 5	Portable restroom, near Rooms B18 - B20, exterior free standing two station, upper bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist