

Water Quality Chemistry Services
 Lead School Testing
 Report Date: 28-Apr-2017

San Diego Unified School District
Ballard Parent Center

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168009	4/21/2017	6:20 AM	SAMPLE 1	3710020-AHI-A	< 5	µg/L
W1168010	4/21/2017	6:26 AM	SAMPLE 2	3710020-AHI-B	10.0	µg/L
W1168011	4/21/2017	6:23 AM	SAMPLE 3	3710020-AHI-C	< 5	µg/L
W1168012	4/21/2017	6:18 AM	SAMPLE 4	3710020-AHI-D	< 5	µg/L
W1168013	4/21/2017	6:10 AM	SAMPLE 5	3710020-AHI-E	< 5	µg/L

- | <u>Source</u> | <u>Source Description</u> |
|---------------|--|
| SAMPLE 1 | Auditorium Bldg.; Outside Bathrooms next to the Auditorium; Upper left bubbler of 2 single fountains |
| SAMPLE 2 | Inside the Workroom/Staff Lounge; faucet the workroom interior sink |
| SAMPLE 3 | Kitchen Bldg; Interior hot and cold faucet on a single compartment metal sink |
| SAMPLE 4 | Building Main Office; Ext. Drinking fountain behind the main office in the playground; left upper bubbler |
| SAMPLE 5 | I High Bldg.; SE end of the bldg.; 2 high/low sets of single fountains; Upper L bubbler of the R set of single fountains |

DRL=State Mandated Detection Limit for Reporting (DLR)= 5 µg/L
 Action Level (AL) = 15 µg/L



Doug Campbell, Senior Chemist