



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Bay Park Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169385	05/11/17	06:18 AM	SAMPLE 1	3710020-BEA-A	< 5	ug/L
W1169386	05/11/17	06:08 AM	SAMPLE 2	3710020-BEA-B	< 5	ug/L
W1169387	05/11/17	06:05 AM	SAMPLE 3	3710020-BEA-C	< 5	ug/L
W1169388	05/11/17	06:13 AM	SAMPLE 4	3710020-BEA-D	< 5	ug/L
W1171698	05/11/17	06:22 AM	SAMPLE 5	3710020-BEA-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    East facing exterior wall next to blacktop area backside of room 5, triple bubbler fountain, right bubbler
- SAMPLE 2    North side of lunch arbor next to cafeteria, quintuple bubbler fountain, far right bubbler
- SAMPLE 3    Kitchen, East interior wall next to range, faucet above single compartment sink
- SAMPLE 4    Kindergarten bldg, West interior wall, bubbler at sink
- SAMPLE 5    Restroom Bungalow, East exterior side between boy & girl's RR, two single-bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist