



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17

San Diego Unified School District
Bell Middle School

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164188	04/05/17	06:20 AM	SAMPLE 1	3710020-ABE-A	< 5	ug/L
W1164189	04/05/17	06:00 AM	SAMPLE 2	3710020-ABE-B	< 5	ug/L
W1164190	04/05/17	06:05 AM	SAMPLE 3	3710020-ABE-C	< 5	ug/L
W1164191	04/05/17	06:10 AM	SAMPLE 4	3710020-ABE-D	< 5	ug/L
W1164192	04/05/17	06:15 AM	SAMPLE 5	3710020-ABE-E	< 5	ug/L

Sample # Sample Site

- SAMPLE 1 BLDG 1300; Rm 1308(nurse) bubbler
- SAMPLE 2 Cafeteria/Auditorium; lower faucet at two bowl sink
- SAMPLE 3 Library BLDG 1100, west wall, upper/right bubbler
- SAMPLE 4 PE BLDG 1200, north wall,next girls locker room, upper/left bubbler
- SAMPLE 5 Physical Ed BLDG 1200; west wall, next boys locker room, upper/left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist