



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Bird Rock Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170043	05/11/17	06:10 AM	SAMPLE 1	3710020-BEJ-A	10.5	ug/L
W1170044	05/11/17	06:15 AM	SAMPLE 2	3710020-BEJ-B	< 5	ug/L
W1170045	05/11/17	05:55 AM	SAMPLE 3	3710020-BEJ-C	< 5	ug/L
W1170046	05/11/17	06:05 AM	SAMPLE 4	3710020-BEJ-D	< 5	ug/L
W1170047	05/11/17	06:00 AM	SAMPLE 5	3710020-BEJ-E	< 5	ug/L

Source	Source Description
SAMPLE 1	Kindergarten, Inside # K-2, Bubblers drinking fountain at hand washing sink
SAMPLE 2	Kindergarten K-3, Bubblers drinking fountain at sink
SAMPLE 3	Auditorium, Outside between men's & women's RRs near lunch court, two single-bubbler fountains, lower left fountain
SAMPLE 4	Cafeteria, Inside Kitchen, Single faucet at 2-compartment sink
SAMPLE 5	Bldg 1-7 rooms, Outside at lower playground, triple bubbler fountain below tree artwork on wall, middle bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist