



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Central Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168072	05/03/17	05:31 AM	SAMPLE 1	3710020-BAB-A	< 5	ug/L
W1168073	05/03/17	05:34 AM	SAMPLE 2	3710020-BAB-B	< 5	ug/L
W1168074	05/03/17	05:36 AM	SAMPLE 3	3710020-BAB-C	< 5	ug/L
W1168075	05/03/17	05:41 AM	SAMPLE 4	3710020-BAB-D	< 5	ug/L
W1168076	05/03/17	05:46 AM	SAMPLE 5	3710020-BAB-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Main Office Building, Outside North End of Campus Downstairs near Nurse's Office, two single bubbler fountains, upper right fountain
- SAMPLE 2      Cafeteria, Under covered lunch patio, two single bubbler fountains, lower left fountain
- SAMPLE 3      Cafeteria/Kitchen, Interior sink located in Southeast corner of kitchen, single faucet above two basin sink
- SAMPLE 4      Northwest side of campus interior court yard, two single bubbler fountains, lower left fountain
- SAMPLE 5      Bungalows, Room 53 at the Southwest corner of the campus, Bubbler on right side of sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist