



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17


San Diego Unified School District
Challenger Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169409	05/05/17	06:05 AM	SAMPLE 1	3710020-BEE-A	< 5	ug/L
W1169410	05/05/17	06:07 AM	SAMPLE 2	3710020-BEE-B	< 5	ug/L
W1169411	05/05/17	06:10 AM	SAMPLE 3	3710020-BEE-C	< 5	ug/L
W1169412	05/05/17	06:12 AM	SAMPLE 4	3710020-BEE-D	< 5	ug/L
W1169413	05/05/17	06:15 AM	SAMPLE 5	3710020-BEE-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Food Service Facility, Wall mounted exterior (West of Bldg), facing lunch court, two single bubbler fountains, upper right fountain
- SAMPLE 2 PE Complex, Wall mounted exterior (South of Bldg), next to Boys Restroom, facing lunch court, two single bubbler fountains, lower left fountain
- SAMPLE 3 PE Complex, Wall mounted exterior (West of Bldg-RIGHT side fountain), next to Boys Locker Rm, dual bubbler fountain, left bubbler
- SAMPLE 4 PE Complex, Wall mounted exterior (West of Bldg-LEFT side fountain), next to Girls' Locker Rm, facing P.E. fields, dual bubbler fountain, left bubbler
- SAMPLE 5 PE Complex, Wall mounted exterior (North of Bldg), next to Girls' RR, facing PE Tennis Court, two single bubbler fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist