



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Cherokee Point Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168277	05/03/17	06:08 AM	SAMPLE 1	3710020-AHD-A	< 5	ug/L
W1168278	05/03/17	06:21 AM	SAMPLE 2	3710020-AHD-B	< 5	ug/L
W1168279	05/03/17	06:18 AM	SAMPLE 3	3710020-AHD-C	< 5	ug/L
W1168280	05/03/17	06:16 AM	SAMPLE 4	3710020-AHD-D	< 5	ug/L
W1168281	05/03/17	06:11 AM	SAMPLE 5	3710020-AHD-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Bldg. C; Wall mounted exterior (E of Bldg), facing lunch court area;upper R bubbler of 2 single fountains
SAMPLE 2	2-Story Building A; Rm A101-Kindergarten, 1st Floor, single bubbler in classroom R side of sink
SAMPLE 3	Ground level Bldg A;Wall-mounted ext. (East of Bldg), facing Bldg D, betw. A107-Mech. Rm & A104-103, towards Kinder Playgr.; Lower L bubbler of 2 single fountains
SAMPLE 4	Bldg D; Rm D102-Kinderg., 1st Floor, classroom sink/faucet;bubbler Rside of sink
SAMPLE 5	Bldg F; Wall mounted ext South side of Bldg, 1st Floor, next to Boys & Girls RRs, facing Playg/Blacktop;Middle bubbler of 3 single fountains

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist