



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/28/17

San Diego Unified School District  
**Chollas/Mead Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166828	04/15/17	06:45 AM	SAMPLE 1	3710020-AEH-A	< 5	ug/L
W1166829	04/15/17	06:41 AM	SAMPLE 2	3710020-AEH-B	< 5	ug/L
W1166830	04/15/17	06:48 AM	SAMPLE 3	3710020-AEH-C	7.73	ug/L
W1166831	04/15/17	06:50 AM	SAMPLE 4	3710020-AEH-D	< 5	ug/L
W1167379	04/19/17	07:00 AM	SAMPLE 5	3710020-AEH-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	CDC building;Outside fountain in playground; pedestal dual fountain upper bubbler
SAMPLE 2	CDC Building;Room # 3103;Right-lower bubbler at sink
SAMPLE 3	Building Cafeteria;Outside drinking fountain in front of Cafeteria;Upper-Right Bubbler
SAMPLE 4	300 Building;Outside Drinking fountain next to restrooms;Middle Bubbler
SAMPLE 5	Kitchen;adjacent to room 501; double compartment sink faucet

DLR= State Mandated Detection Limit for R  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist