



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Clairemont High

| Sample ID | Sample Date | Sample Time | Source | External ID | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1172133 | 05/10/17 | 06:24 AM | SAMPLE 1 | 3710020-BHC-A | < 5 | ug/L |
| W1172134 | 05/10/17 | 06:20 AM | SAMPLE 2 | 3710020-BHC-B | < 5 | ug/L |
| W1172135 | 05/10/17 | 06:30 AM | SAMPLE 3 | 3710020-BHC-C | < 5 | ug/L |
| W1172136 | 05/10/17 | 06:33 AM | SAMPLE 4 | 3710020-BHC-D | < 5 | ug/L |
| W1172137 | 05/10/17 | 06:15 AM | SAMPLE 5 | 3710020-BHC-E | < 5 | ug/L |

Source **Source Description**

- SAMPLE 1 Cafeteria Kitchen, East Interior Wall, spray nozzle above two compartment sink
- SAMPLE 2 Lunch Court Area/ West Exterior Wall, two triple bubbler fountains, middle bubbler on left fountain
- SAMPLE 3 600 BLDG, Girls Lockerroom-East Exterior Wall, triple bubbler fountain, left bubbler
- SAMPLE 4 600 BLDG, Boys Lockerroom / West Exterior Wall, triple bubbler fountain, right bubbler
- SAMPLE 5 100 BLDG, East Exterior Wall at Rm 105/ Boys RR, two dual bubbler fountains, left fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist