



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Dailard Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166508	04/13/17	06:00 AM	SAMPLE 1	3710020-AEE-A	< 5	ug/L
W1166509	04/13/17	06:04 AM	SAMPLE 2	3710020-AEE-B	< 5	ug/L
W1166510	04/13/17	06:08 AM	SAMPLE 3	3710020-AEE-C	< 5	ug/L
W1166511	04/13/17	06:12 AM	SAMPLE 4	3710020-AEE-D	< 5	ug/L
W1166512	04/13/17	06:15 AM	SAMPLE 5	3710020-AEE-E	< 5	ug/L

- | <u>Source</u> | <u>Source Description</u> |
|---------------|---|
| SAMPLE 1 | BLDG 1, next to girls RR, triple fixture, right bubbler |
| SAMPLE 2 | BLDG 2, near RR and room 21, triple fixture, right bubbler |
| SAMPLE 3 | BLDG 5 Library/mutipurpose, between RRrooms, right upper bubbler |
| SAMPLE 4 | Cafe adjacent to bldg 5 near lunch court, triple fixture, right bubbler |
| SAMPLE 5 | BLDG 3, next to RR, triple fixture, right bubbler |

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist