



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/5/17

San Diego Unified School District  
**Einstein Academy**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168287	04/27/17	06:30 AM	SAMPLE 1	3710020-BAC-A	< 5	ug/L
W1168288	04/27/17	05:56 AM	SAMPLE 2	3710020-BAC-B	< 5	ug/L
W1168289	04/27/17	06:02 AM	SAMPLE 3	3710020-BAC-C	< 5	ug/L
W1168290	04/27/17	06:35 AM	SAMPLE 4	3710020-BAC-D	< 5	ug/L
W1168291	04/27/17	06:41 AM	SAMPLE 5	3710020-BAC-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Main office building, Main office building, two compartment kitchen sink
- SAMPLE 2    Main building outside multi purpose room, West wall between boys and girls RR, two single bubbler fountains, upper right fountain
- SAMPLE 3    2 story classroom building, Exterior south wall 1st floor between boys and girls RR, triple bubbler fountain, middle bubbler
- SAMPLE 4    2 story classroom building, 1st floor interior adjacent to boys RR across from room 6, , two single bubbler fountains, lower left fountain
- SAMPLE 5    2 story classroom building, 2nd floor adjacent to staircase across from room 9, dual bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist