



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Field Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170243	05/11/17	06:04 AM	SAMPLE 1	3710020-BEC-A	< 5	ug/L
W1170244	05/11/17	06:00 AM	SAMPLE 2	3710020-BEC-B	< 5	ug/L
W1170245	05/11/17	05:55 AM	SAMPLE 3	3710020-BEC-C	< 5	ug/L
W1170246	05/11/17	05:47 AM	SAMPLE 4	3710020-BEC-D	< 5	ug/L
W1170247	05/11/17	05:51 AM	SAMPLE 5	3710020-BEC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Classrooms 14-19 bldg, triple bubbler fountain, left bubbler
- SAMPLE 2 Classrooms 6-13 bldg, South exterior side next to boy's RR, triple bubbler fountain, left bubbler
- SAMPLE 3 Classrooms 2-4 bldg, Inside classroom 2 on west wall, bubbler at sink
- SAMPLE 4 Kitchen, west interior wall, faucet above 2 compartment sink
- SAMPLE 5 Kindergarten bldg, Exterior east side between K-1 & K-2, single fountain bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist