



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Foster Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166357	04/13/17	06:07 AM	SAMPLE 1	3710020-AED-A	< 5	ug/L
W1166358	04/13/17	06:10 AM	SAMPLE 2	3710020-AED-B	< 5	ug/L
W1166359	04/13/17	06:13 AM	SAMPLE 3	3710020-AED-C	< 5	ug/L
W1166360	04/13/17	06:17 AM	SAMPLE 4	3710020-AED-D	< 5	ug/L
W1166361	04/13/17	06:20 AM	SAMPLE 5	3710020-AED-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 BLDG 3, east end between boys restroom and gear locker, left lower bubbler (111-01)
- SAMPLE 2 BLDG 3, inside room 9, bubbler at sink (111-2)
- SAMPLE 3 BLDG 4, inside room 2, bubbler at sink (111-3)
- SAMPLE 4 BLDG 3, near south end, between boys RR and custodial closet, two fountains, right bubbler on left fountain(111-4)
- SAMPLE 5 BLDG 5, room B-23, bubbler at sink (111-5)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist