



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Green Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166644	04/14/17	05:34 AM	SAMPLE 1	3710020-AEI-A	< 5	ug/L
W1166645	04/14/17	05:36 AM	SAMPLE 2	3710020-AEI-B	< 5	ug/L
W1166646	04/14/17	05:40 AM	SAMPLE 3	3710020-AEI-C	< 5	ug/L
W1166647	04/14/17	05:43 AM	SAMPLE 4	3710020-AEI-D	< 5	ug/L
W1166648	04/14/17	05:29 AM	SAMPLE 5	3710020-AEI-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Multipurpose BLDG, south exterior, near RRoms and room 20, lower left bubbler
SAMPLE 2	K-36 bldg, room 33 back, bubbler in sink
SAMPLE 3	TK-26, east wall next to RR and custodial closet, triple fountain, left bubbler
SAMPLE 4	11-16 BLDG, near playing field between RR, triple fountain, center bubbler
SAMPLE 5	Kitchen, exterior near lunch court, triple fountain, center bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist