



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/28/17

San Diego Unified School District  
**Hearst Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167256	04/18/17	06:11 AM	SAMPLE 1	3710020-AFJ-A	< 5	ug/L
W1167257	04/18/17	06:13 AM	SAMPLE 2	3710020-AFJ-B	< 5	ug/L
W1167258	04/18/17	06:15 AM	SAMPLE 3	3710020-AFJ-C	< 5	ug/L
W1167259	04/18/17	06:17 AM	SAMPLE 4	3710020-AFJ-D	< 5	ug/L
W1167260	04/18/17	06:20 AM	SAMPLE 5	3710020-AFJ-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Auditorium/Serving RM; Inside serving room near kitchen roll up door; R side bubbler on a single 3-fixture white sink
- SAMPLE 2    1-5 bldg.; Exterior west end near black top playground and Lunch court; Lower L side of 2 single fountains
- SAMPLE 3    7-12 BLDG; west end near black top playground basketball area;L side bubbler of a 3-bubbler water fountain
- SAMPLE 4    1-6 BLDG; N exterior wall; L bubbler of 3-bubbler fountain near corner
- SAMPLE 5    Kinder play ground; Outside kinder classrooms between toy storage doors; Lower L side bubbler of 2 separate single fountains

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

*Tom B. Burger*  
Tom Burger, Associate Chemist