



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/28/17

San Diego Unified School District
Holly Drive Leadership

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166990	04/19/17	05:50 AM	SAMPLE 1	3710020-AFH-A	< 5	ug/L
W1166991	04/19/17	05:55 AM	SAMPLE 2	3710020-AFH-B	< 5	ug/L
W1166992	04/19/17	06:07 AM	SAMPLE 3	3710020-AFH-C	< 5	ug/L
W1166993	04/19/17	05:59 AM	SAMPLE 4	3710020-AFH-D	< 5	ug/L
W1166994	04/19/17	06:03 AM	SAMPLE 5	3710020-AFH-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Room B-21 Bubbler in sink
SAMPLE 2	Room B-19 Bubbler in sink
SAMPLE 3	Room B-17 Bubbler in sink
SAMPLE 4	Room B-16 Bubbler in sink
SAMPLE 5	Room B-14 Bubbler in sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist