



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Kimbrough Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168353	05/04/17	06:05 AM	SAMPLE 1	3710020-BBB-A	< 5	ug/L
W1168354	05/04/17	06:09 AM	SAMPLE 2	3710020-BBB-B	5.05	ug/L
W1168355	05/04/17	06:00 AM	SAMPLE 3	3710020-BBB-C	< 5	ug/L
W1168356	05/04/17	06:13 AM	SAMPLE 4	3710020-BBB-D	< 5	ug/L
W1168357	05/04/17	06:15 AM	SAMPLE 5	3710020-BBB-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Multipurpose Bldg., North wall of Kitchen, Faucet on a two-compartment sink
SAMPLE 2	Restrooms Bldg, South wall, two single bubbler fountains, lower left fountain
SAMPLE 3	Administration Bldg., East wall, four single bubbler fountains, far left fountain
SAMPLE 4	Classroom Bldg. 100, West wall of restrooms near room 105, five single bubbler fountains, middle fountain
SAMPLE 5	Classroom Bldg. 100, West wall of restrooms near room 110, five single bubbler fountains, middle fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist