



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Kumeyaay Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169360	05/06/17	05:51 AM	SAMPLE 1	3710020-BDG-A	< 5	ug/L
W1169361	05/06/17	06:05 AM	SAMPLE 2	3710020-BDG-B	< 5	ug/L
W1169362	05/06/17	06:01 AM	SAMPLE 3	3710020-BDG-C	< 5	ug/L
W1169363	05/06/17	05:55 AM	SAMPLE 4	3710020-BDG-D	< 5	ug/L
W1169364	05/06/17	05:49 AM	SAMPLE 5	3710020-BDG-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten Building, Outside East facing wall, Triple bubbler fountain left of a single bubbler fountain, left bubbler on triple fountain
SAMPLE 2	Library/Media and RR building, Center of campus east side of building between RRs, Triple bubbler fountain right of a single bubbler fountain, right bubbler
SAMPLE 3	Library/Media and RR building, Center of campus east side of building between RRs, Triple bubbler fountain left of a single bubbler fountain, middle bubbler
SAMPLE 4	Bungalow K-5 (marked as K-3 on map), East end of kindergarten area, bubbler at sink
SAMPLE 5	Kindergarten Building Room K-2, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist