



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Progress Report

Date of Report: 1/9/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin - Fulton_01-03 Common Area/Lounge - LGE1, West Wall	DWO-119-001	Faucet	33.34		
2	3 Admin - Fulton_01-03 Nurse Office - HLC1, North Wall	DWO-119-002	Faucet	3.67		
3	2 Classrooms 1-6 - Fulton_01-02 Classroom - 01, East Wall	DWO-119-003	Drinking Fountain Bubblers	2.88		
4	2 Classrooms 1-6 - Fulton_01-02 Classroom - 02, East Wall	DWO-119-004	Drinking Fountain Bubblers	5.37		
5	2 Classrooms 1-6 - Fulton_01-02 Classroom - 03, East Wall	DWO-119-005	Drinking Fountain Bubblers	5.21		
6	2 Classrooms 1-6 - Fulton_01-02 Classroom - 04, West Wall	DWO-119-006	Drinking Fountain Bubblers	ND		
7	2 Classrooms 1-6 - Fulton_01-02 Classroom - 05, West Wall	DWO-119-007	Drinking Fountain Bubblers	3.37		
8	2 Classrooms 1-6 - Fulton_01-02 Classroom - 06, West Wall	DWO-119-008	Drinking Fountain Bubblers	5.11		
9	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-009	Drinking Fountain Bubblers	4.32		
10	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-010	Drinking Fountain Bubblers	ND		
11	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-011	Drinking Fountain Bubblers	<5		
12	1 Classrooms 7-12 - Fulton_01-01 Classroom - 07, East Wall	DWO-119-012	Drinking Fountain Bubblers	ND		
13	1 Classrooms 7-12 - Fulton_01-01 Classroom - 08, East Wall	DWO-119-013	Drinking Fountain Bubblers	ND		
14	1 Classrooms 7-12 - Fulton_01-01 Classroom - 09, East Wall	DWO-119-014	Drinking Fountain Bubblers	2.71		
15	1 Classrooms 7-12 - Fulton_01-01 Classroom - 10, West Wall	DWO-119-015	Drinking Fountain Bubblers	2.94		
16	1 Classrooms 7-12 - Fulton_01-01 Classroom - 11, West Wall	DWO-119-016	Drinking Fountain Bubblers	2.89		
17	1 Classrooms 7-12 - Fulton_01-01 Classroom - 12, West Wall	DWO-119-017	Drinking Fountain Bubblers	5.61		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Progress Report

Date of Report: 1/9/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18 1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-018	Drinking Fountain Bubblers	6.07		
19 1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-019	Drinking Fountain Bubblers	4.26		
20 1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-020	Drinking Fountain Bubblers	3.71		
21 7 Classrooms 13-16 - Fulton_02-07 Classroom - 13, West Wall	DWO-119-021	Drinking Fountain Bubblers	ND		
22 7 Classrooms 13-16 - Fulton_02-07 Classroom - 14, West Wall	DWO-119-022	Drinking Fountain Bubblers	ND		
23 7 Classrooms 13-16 - Fulton_02-07 Classroom - 15, West Wall	DWO-119-023	Drinking Fountain Bubblers	ND		
24 7 Classrooms 13-16 - Fulton_02-07 Classroom - 16, West Wall	DWO-119-024	Drinking Fountain Bubblers	ND		
25 Portable A05 - Fulton Classroom - A05, West Wall	DWO-119-025	Drinking Fountain Bubblers	3.50		
26 Portable A04 - Fulton Classroom - A04, West Wall	DWO-119-026	Drinking Fountain Bubblers	2.59		
27 Portable A07 - Fulton Classroom - A07, East Wall	DWO-119-027	Drinking Fountain Bubblers	ND		
28 Portable B12/B13 - Fulton Science Prep Area - B13A, South Wall	DWO-119-028	Faucet	ND		
29 Portable Restrooms - Fulton Building Exterior, North Wall	DWO-119-029	Drinking Fountain Bubblers	ND		
30 Portable Restrooms - Fulton Building Exterior, North Wall	DWO-119-030	Drinking Fountain Bubblers	ND		
31 Portable Restrooms - Fulton Building Exterior, West side of BLDG	DWO-119-031	Drinking Fountain Bubblers	2.82		
32 Portable Restrooms - Fulton Building Exterior, West side of BLDG	DWO-119-032	Drinking Fountain Bubblers	<5		
33 4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Building Exterior, West Wall	DWO-119-033	Drinking Fountain Bubblers	3.05		
34 4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Building Exterior, West Wall	DWO-119-034	Drinking Fountain Bubblers	<5		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Progress Report

Date of Report: 1/9/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Kitchen, North Wall	DWO-119-035	Faucet	<5		
36	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Lounge by Supply Rm, West Wall	DWO-119-036	Faucet	ND		
37	6 Library - Fulton_02-06 Office - OFS1, North Wall	DWO-119-037	Faucet	6.19		
38	Portable B08 - Fulton Classroom - B08, West Wall	DWO-119-038	Drinking Fountain Bubblers	ND		
39	Portable B09 - Fulton Classroom - B09, East Wall	DWO-119-039	Drinking Fountain Bubblers	3.35		
40	Portable B10 - Fulton Classroom - B10, West Wall	DWO-119-040	Drinking Fountain Bubblers	3.64		
41	Portable B11 - Fulton Classroom - B11, East Wall	DWO-119-041	Drinking Fountain Bubblers	3.69		
42	5 Kinder Rms K01-K02 - Fulton_01-05 Classroom - K02, West Wall	DWO-119-042	Drinking Fountain Bubblers	5.57		
43	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-043	Drinking Fountain Bubblers	19.58		
44	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-044	Drinking Fountain Bubblers	5.51		
45	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-045	Drinking Fountain Bubblers	5.81		
46	5 Kinder Rms K01-K02 - Fulton_01-05 Classroom - K01, West Wall	DWO-119-046	Drinking Fountain Bubblers	4.64		
47	3 Admin - Fulton_01-03 Faculty Workroom - WRK1, south wall	DWO-119-047	Faucet	10.51		
48	Portable K03 - Fulton Restroom/Student Male - K03T2, island sink	DWO-119-048	Drinking Fountain Bubblers	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Progress Report

Date of Report: 1/9/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.