



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Left	DWO-162-001	Faucet	2.57		
2	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Center Left	DWO-162-002	Faucet	ND		
3	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Center Right	DWO-162-003	Drinking Fountain Bubbler	<5		
4	3 Admin/Supply - Kimbrough_01-03 Building Exterior, East Wall Right	DWO-162-004	Drinking Fountain Bubbler	ND		
5	3 Admin/Supply - Kimbrough_01-03 Nurse Health, North Wall	DWO-162-005	Drinking Fountain Bubbler	ND		
6	3 Admin/Supply - Kimbrough_01-03 Lounge, East Wall	DWO-162-006	Drinking Fountain Bubbler	ND		
7	3 Admin/Supply - Kimbrough_01-03 Community Rm, East Wall	DWO-162-007	Faucet	3.76		
8	Portable B02 - Kimbrough Workshop, East Wall	DWO-162-008	Faucet	<5		
9	Portable B04 - Kimbrough Classroom - B04 Multi-Purpose, East Wall	DWO-162-009	Drinking Fountain Bubbler	ND		
10	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 101, West Wall	DWO-162-010	Drinking Fountain Bubbler	ND		
11	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 102, West Wall	DWO-162-011	Faucet	3.57		
12	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 103, West Wall	DWO-162-012	Drinking Fountain Bubbler	ND		
13	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 104, West Wall	DWO-162-013	Drinking Fountain Bubbler	ND		
14	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 105, East Wall	DWO-162-014	Faucet	4.53		
15	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 105, West Wall	DWO-162-015	Drinking Fountain Bubbler	ND		
16	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 106, East Wall	DWO-162-016	Drinking Fountain Bubbler	ND		
17	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 107, Westwall	DWO-162-017	Drinking Fountain Bubbler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 108, West Wall	DWO-162-018	Faucet	2.96		
19	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 108, West Wall	DWO-162-019	Drinking Fountain Bubblers	ND		
20	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 110, East Wall	DWO-162-020	Drinking Fountain Bubblers	3.05		
21	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 111, East Wall	DWO-162-021	Drinking Fountain Bubblers	ND		
22	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 112, West Wall	DWO-162-022	Drinking Fountain Bubblers	2.61		
23	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 113, West Wall	DWO-162-023	Drinking Fountain Bubblers	ND		
24	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 201, East Wall	DWO-162-024	Drinking Fountain Bubblers	<5		
25	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 202, East Wall	DWO-162-025	Drinking Fountain Bubblers	ND		
26	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 202, South Wall	DWO-162-026	Drinking Fountain Bubblers	ND		
27	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 203, East Wall	DWO-162-027	Drinking Fountain Bubblers	ND		
28	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 204, East Wall	DWO-162-028	Drinking Fountain Bubblers	ND		
29	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 205, East Wall	DWO-162-029	Drinking Fountain Bubblers	ND		
30	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 206, East Wall	DWO-162-030	Drinking Fountain Bubblers	ND		
31	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 208, East Wall	DWO-162-031	Drinking Fountain Bubblers	ND		
32	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 208, East Wall	DWO-162-032	Drinking Fountain Bubblers	<5		
33	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 209, East Wall	DWO-162-033	Drinking Fountain Bubblers	ND		
34	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 210, Southeast Right	DWO-162-034	Drinking Fountain Bubblers	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 211, West Wall	DWO-162-035	Drinking Fountain Bubblers	ND		
36	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 212, East Wall	DWO-162-036	Drinking Fountain Bubblers	ND		
37	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 213, East Wall	DWO-162-037	Drinking Fountain Bubblers	ND		
38	5 100/200 Classrooms - Kimbrough_01-05 Classroom - 213, West Wall	DWO-162-038	Drinking Fountain Bubblers	ND		
39	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Right	DWO-162-039	Drinking Fountain Bubblers	ND		
40	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Left	DWO-162-040	Drinking Fountain Bubblers	ND		
41	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Left	DWO-162-041	Drinking Fountain Bubblers	ND		
42	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Left	DWO-162-042	Drinking Fountain Bubblers	ND		
43	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Center Right	DWO-162-043	Drinking Fountain Bubblers	ND		
44	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southeast Right	DWO-162-044	Drinking Fountain Bubblers	ND		
45	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Right	DWO-162-045	Drinking Fountain Bubblers	ND		
46	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Center Right	DWO-162-046	Drinking Fountain Bubblers	ND		
47	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Center Right	DWO-162-047	Faucet	ND		
48	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Left Center	DWO-162-048	Drinking Fountain Bubblers	ND		
49	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Southwest Side Left	DWO-162-049	Drinking Fountain Bubblers	ND		
50	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Left	DWO-162-050	Drinking Fountain Bubblers	ND		
51	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center Left	DWO-162-051	Drinking Fountain Bubblers	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
52	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center	DWO-162-052	Drinking Fountain Bubblers	ND		
53	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Center Right	DWO-162-053	Drinking Fountain Bubblers	ND		
54	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northwest Central Right	DWO-162-054	Drinking Fountain Bubblers	ND		
55	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Left	DWO-162-055	Drinking Fountain Bubblers	ND		
56	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Left	DWO-162-056	Drinking Fountain Bubblers	ND		
57	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Left	DWO-162-057	Drinking Fountain Bubblers	ND		
58	5 100/200 Classrooms - Kimbrough_01-05 Building Exterior, Northeast Central Center Right	DWO-162-058	Faucet	ND		
59	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 101/102, South Wall	DWO-162-059	Drinking Fountain Bubblers	ND		
60	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 104-107, South Wall	DWO-162-060	Drinking Fountain Bubblers	5.05		
61	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 109-112, South Wall	DWO-162-061	Drinking Fountain Bubblers	2.82		
62	5 100/200 Classrooms - Kimbrough_01-05 Workroom in 204-207, East Wall	DWO-162-062	Drinking Fountain Bubblers	2.82		
63	4 Kitchen/Multi-Purpose - Kimbrough_01-04 Kitchen, North Wall	DWO-162-063	Drinking Fountain Bubblers	3.04		
64	Portables 114/214 - Kimbrough Classroom - 114, South Wall	DWO-162-064	Drinking Fountain Bubblers	ND		
65	Portables 114/214 - Kimbrough Classroom - 214, South Wall	DWO-162-065	Drinking Fountain Bubblers	ND		
66	Portables 115/215 - Kimbrough Classroom - 115, South Wall	DWO-162-066	Drinking Fountain Bubblers	3.84		
67	Portables 115/215 - Kimbrough Classroom - 215, South Wall	DWO-162-067	Drinking Fountain Bubblers	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
68	Portables 116/216 - Kimbrough Classroom - 116, North Wall	DWO-162-068	Drinking Fountain Bubblers	ND		
69	Portables 116/216 - Kimbrough Classroom - 116, North Wall	DWO-162-069	Drinking Fountain Bubblers	19.39		
70	Portables 116/216 - Kimbrough Classroom - 216, North Wall	DWO-162-070	Drinking Fountain Bubblers	2.76		
71	Portables 117/217 - Kimbrough Classroom - 217, East Wall	DWO-162-071	Drinking Fountain Bubblers	ND		
72	1 Kinder Rms K03-K05 - Kimbrough_01-01 Building Exterior, East Wall Left	DWO-162-072	Drinking Fountain Bubblers	7.29		
73	1 Kinder Rms K03-K05 - Kimbrough_01-01 Building Exterior, East Wall Right	DWO-162-073	Drinking Fountain Bubblers	ND		
74	1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K03, East Wall	DWO-162-074	Faucet	3.76		
75	1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K04, East Wall	DWO-162-075	Faucet	2.52		
76	1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Right	DWO-162-076	Faucet	2.81		
77	1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Left	DWO-162-077	Drinking Fountain Bubblers	2.74		
78	1 Kinder Rms K03-K05 - Kimbrough_01-01 Classroom - K05, East Wall Right Sink	DWO-162-078	Drinking Fountain Bubblers	ND		
79	Portables 118/218 - Kimbrough Classroom - 118, West Wall	DWO-162-079	Drinking Fountain Bubblers	ND		
80	Portables 118/218 - Kimbrough Classroom - 118, East Wall	DWO-162-080	Drinking Fountain Bubblers	ND		
81	Portables 118/218 - Kimbrough Classroom - 218, West Wall	DWO-162-081	Drinking Fountain Bubblers	2.94		
82	Portables 119/219 - Kimbrough Classroom - 119, East Wall	DWO-162-083	Drinking Fountain Bubblers	2.98		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kimbrough ES

Report Type: Progress Report

Date of Report: 12/21/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
83 Portables 119/219 - Kimbrough Classroom - 219, East Wall	DWO-162-084	Faucet	ND		
84 2 Kinder Rms K01-K02/Learning Center - Kimbrough_01-02	DWO-162-085	Faucet	ND		
85 2 Kinder Rms K01-K02/Learning Center - Kimbrough_01-02	DWO-162-091	Faucet	ND		
86 2 Kinder Rms K01-K02/Learning Center - Kimbrough_01-02	DWO-162-092	Faucet	ND		
87 6 Restrooms - Kimbrough_01-06 Building Exterior, West Wall Left	DWO-162-093	Faucet	ND		
88 6 Restrooms - Kimbrough_01-06 Building Exterior, West Wall Right	DWO-162-094	Faucet	ND		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.