



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Tubman Charter

Report Type: Progress Report

Date of Report: 04/11/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
2 Admin/Classrooms - Harriet Tubman_02-02 Office Counselers, east wall	DWO-214-001	Faucet	4.49		
2 Admin/Classrooms - Harriet Tubman_02-02 Nurse Office, west wall	DWO-214-002	Drinking Fountain Bubblers	1.87		
2 Admin/Classrooms - Harriet Tubman_02-02 Classroom - 02, east wall	DWO-214-003	Drinking Fountain Bubblers	0.46		
2 Admin/Classrooms - Harriet Tubman_02-02 Classroom - 05, west wall	DWO-214-004	Drinking Fountain Bubblers	0.71		
2 Admin/Classrooms - Harriet Tubman_02-02 Classroom - 03, east wall	DWO-214-005	Drinking Fountain Bubblers	0.58		
2 Admin/Classrooms - Harriet Tubman_02-02 Classroom - 04, west wall	DWO-214-006	Drinking Fountain Bubblers	0.94		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, northeast wall left side	DWO-214-007	Drinking Fountain Bubblers	1.55		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, northeast wall middle left	DWO-214-008	Drinking Fountain Bubblers	0.89		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, northeast wall middle right	DWO-214-009	Drinking Fountain Bubblers	0.95		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, northeast wall right side	DWO-214-010	Drinking Fountain Bubblers	1.02		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, middle north wall left side	DWO-214-011	Drinking Fountain Bubblers	2.09		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, middle north wall middle left	DWO-214-012	Drinking Fountain Bubblers	1.84		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, middle north wall middle right	DWO-214-013	Drinking Fountain Bubblers	<5		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Building Exterior, middle north wall right side.	DWO-214-014	Drinking Fountain Bubblers	3.86		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Multi-Purpose Rm, north wall	DWO-214-015	Drinking Fountain Bubblers	2.22		
3 Multi-Purpose/Kitchen - Harriet Tubman_03-03 Kitchen, west wall	DWO-214-016	Faucet	9.84		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Tubman Charter

Report Type: Progress Report

Date of Report: 04/11/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	4 Kinder Rms 1-2 - Harriet Tubman_03-04 Classroom - KG1, east wall	DWO-214-017	Drinking Fountain Bubblers	1.98		
18	4 Kinder Rms 1-2 - Harriet Tubman_03-04 Classroom - KG1, east wall	DWO-214-018	Drinking Fountain Bubblers	<5		
19	5 Library - Harriet Tubman_04-05 Restroom Faculty Uni-sex, South Wall	DWO-214-019	Faucet	0.39		
20	Portable B12 - Harriet Tubman Classroom - B12, west wall	DWO-214-020	Drinking Fountain Bubblers	0.35		
21	Portable B11 - Harriet Tubman Classroom - B11, west wall	DWO-214-021	Drinking Fountain Bubblers	0.35		
22	Portable B10 - Harriet Tubman Classroom - B10, west wall	DWO-214-022	Drinking Fountain Bubblers	0.36		
23	Portable B09 - Harriet Tubman Classroom - B09, west wall	DWO-214-023	Drinking Fountain Bubblers	0.59		
24	Portable B13 - Harriet Tubman Classroom - B13, east wall	DWO-214-024	Drinking Fountain Bubblers	0.56		
25	Portable B14 - Harriet Tubman Classroom - B14, east wall	DWO-214-025	Drinking Fountain Bubblers	0.32		
26	Portable B16 - Harriet Tubman Classroom - B16, west wall	DWO-214-026	Drinking Fountain Bubblers	0.45		
27	Portable B17 - Harriet Tubman Classroom - B17, west wall	DWO-214-027	Drinking Fountain Bubblers	0.42		
28	Portable B18 - Harriet Tubman Classroom - B18, west wall	DWO-214-028	Drinking Fountain Bubblers	0.31		
29	Portable B15 - Harriet Tubman , west wall	DWO-214-029	Drinking Fountain Bubblers	4.03		
30	Portable B08 - Harriet Tubman Classroom - B08, north wall	DWO-214-030	Drinking Fountain Bubblers	2.08		
31	Portable B07 - Harriet Tubman Lounge, north wall	DWO-214-031	Drinking Fountain Bubblers	11.02		
32	Portable B06 - Harriet Tubman Classroom - B06, north wall	DWO-214-032	Drinking Fountain Bubblers	0.95		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Tubman Charter

Report Type: Progress Report

Date of Report: 04/11/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33	2 Admin/Classrooms - Harriet Tubman_02-02 Building Exterior, west wall left side	DWO-214-033	Drinking Fountain Bubblers	0.37		
34	2 Admin/Classrooms - Harriet Tubman_02-02 Building Exterior, west wall middle	DWO-214-034	Drinking Fountain Bubblers	<5		
35	2 Admin/Classrooms - Harriet Tubman_02-02 Building Exterior, west wall right side	DWO-214-035	Drinking Fountain Bubblers	0.33		
36	2 Admin/Classrooms - Harriet Tubman_02-02 Conference Rm, N wall	DWO-214-036	Faucet	1.14		
37	4 Kinder Rms 1-2 - Harriet Tubman_03-04 Building Exterior, pedestal drinking fountain s side of bldg	DWO-214-037	Drinking Fountain Bubblers	NA		
38	4 Kinder Rms 1-2 - Harriet Tubman_03-04 Building Exterior, pedestal drinking fountain s side of bldg	DWO-214-038	Drinking Fountain Bubblers	NA		
39	Portable Restrooms by B16 - Harriet Tubman Restroom Student Female, pedestal drinking fountain N	DWO-214-039	Drinking Fountain Bubblers	ND		
40	Portable Restrooms by B16 - Harriet Tubman Restroom Student Female, pedestal drinking fountain N	DWO-214-040	Drinking Fountain Bubblers	<5		
41	Portable Restrooms by B06 - Harriet Tubman Building Exterior, S side of ramp, left bubbler	DWO-214-041	Drinking Fountain Bubblers	0.57		
42	Portable Restrooms by B06 - Harriet Tubman Building Exterior, S side of ramp, right bubbler	DWO-214-042	Drinking Fountain Bubblers	0.43		

*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Tubman Charter

Report Type: Progress Report

Date of Report: 04/11/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------