



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17


San Diego Unified School District
Lindbergh/Schweitzer Elementary East

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171840	05/13/17	06:46 AM	SAMPLE 1	3710020-BHA-A	< 5	ug/L
W1171841	05/13/17	06:32 AM	SAMPLE 2	3710020-BHA-B	< 5	ug/L
W1171842	05/13/17	06:35 AM	SAMPLE 3	3710020-BHA-C	< 5	ug/L
W1171843	05/13/17	06:39 AM	SAMPLE 4	3710020-BHA-D	< 5	ug/L
W1171844	05/13/17	06:42 AM	SAMPLE 5	3710020-BHA-E	7.98	ug/L

Source **Source Description**

- SAMPLE 1 Library, East exterior wall of library between RRs, three single bubbler fountains, middle fountain
- SAMPLE 2 Auditorium/Cafeteria, South exterior wall next to auditorium/cafeteria door, dual bubbler fountain, left bubbler
- SAMPLE 3 Wing 50-58, Interior hallway next to girl's restroom, dual bubbler fountain, right bubbler
- SAMPLE 4 Inside room 71, north wall, bubbler on right side of sink
- SAMPLE 5 Restroom Bungalow, South exterior side, dual bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist