



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Loma Portal Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173086	05/24/17	05:57 AM	SAMPLE 1	3710020-CAC-A	< 5	ug/L
W1173087	05/24/17	06:00 AM	SAMPLE 2	3710020-CAC-B	< 5	ug/L
W1173088	05/24/17	06:08 AM	SAMPLE 3	3710020-CAC-C	< 5	ug/L
W1173089	05/24/17	06:03 AM	SAMPLE 4	3710020-CAC-D	< 5	ug/L
W1173090	05/24/17	05:53 AM	SAMPLE 5	3710020-CAC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Office, Wall mounted exterior (West of Bldg), facing lunch court, two single bubbler fountains, upper right fountain
- SAMPLE 2 Rooms 3-7, Hallway, next to Boiler Room, facing Classroom 5, single bubbler fountain
- SAMPLE 3 Portable Restrooms and B25, Wall mounted exterior (North of Bldg), between Girls and Boys RRs, facing B27, two triple bubbler fountains, right bubbler on right fountain
- SAMPLE 4 Kindergarten, Wall mounted exterior (South of Bldg), between K2 and K1, facing Kindergarten playground & tables, triple bubbler fountain, middle bubbler
- SAMPLE 5 Portable 32 & Supplies Room, Wall mounted exterior (West of Bldg), facing Playground, two triple bubbler fountains, middle bubbler on left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist