



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Marcy School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168786	05/23/17	06:08 AM	SAMPLE 1	3710020-BDF-A	< 5	ug/L
W1168787	05/23/17	06:57 AM	SAMPLE 2	3710020-BDF-B	< 5	ug/L
W1168788	05/23/17	06:55 AM	SAMPLE 3	3710020-BDF-C	< 5	ug/L
W1168789	05/23/17	07:01 AM	SAMPLE 4	3710020-BDF-D	< 5	ug/L
W1168790	05/23/17	06:14 AM	SAMPLE 5	3710020-BDF-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	restroom BLDG, west side of campus near Sicard St., upper left bubbler
SAMPLE 2	portable classroom 8, NE corner, bubbler at sink
SAMPLE 3	portable classroom 10, NE corner, bubbler at sink
SAMPLE 4	portable classroom 1, SW corner, bubbler at sink
SAMPLE 5	restroom BLDG, north side of campus near Julian AVE, lower right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist