



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

**Mission Bay Montessori**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174388	05/25/17	06:35 AM	SAMPLE 1	3710020-CBA-A	< 5	ug/L
W1174389	05/25/17	06:30 AM	SAMPLE 2	3710020-CBA-B	< 5	ug/L
W1174390	05/25/17	06:30 AM	SAMPLE 3	3710020-CBA-C	< 5	ug/L
W1174391	05/25/17	06:40 AM	SAMPLE 4	3710020-CBA-D	< 5	ug/L
W1174392	05/25/17	06:45 AM	SAMPLE 5	3710020-CBA-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Kindergarten bldg, North wall of Room K1, bubbler at sink
- SAMPLE 2    Kindergarten bldg, Exterior east walkway, triple bubbler fountain, middle bubbler
- SAMPLE 3    Cafeteria bldg, Exterior south wall, breezeway between cafeteria and Administration
- SAMPLE 4    Northeastern classroom bldg. rooms 7 to 12, Exterior West wall, adjacent to RRs, triple bubbler fountain, middle bubbler
- SAMPLE 5    Southeastern classroom bldg. rooms 1 to 6, Exterior East wall Adjacent to RRs, triple bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist