



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17


San Diego Unified School District
Millennial Tech Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165131	04/07/17	05:41 AM	SAMPLE 1	3710020-ACF-A	< 5	ug/L
W1165132	04/07/17	05:43 AM	SAMPLE 2	3710020-ACF-B	< 5	ug/L
W1165133	04/07/17	05:46 AM	SAMPLE 3	3710020-ACF-C	< 5	ug/L
W1165134	04/07/17	05:49 AM	SAMPLE 4	3710020-ACF-D	< 5	ug/L
W1165135	04/07/17	05:52 AM	SAMPLE 5	3710020-ACF-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Center court, east exterior wall, dual fixture, right bubbler (341-01)
- SAMPLE 2 Center court, west exterior wall, dual fixture, right bubbler (341-02)
- SAMPLE 3 BLDG 200, exterior, next to Room 204, dual fixture, left bubbler (341-03)
- SAMPLE 4 BLDG 100, exterior, next to Room 104, dual fixture, right bubbler (341-04)
- SAMPLE 5 Main office BLDG, east end, near men's restroom 3, single bubbler (341-05)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist