



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/19/17


San Diego Unified School District  
**Pacific View Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165314	04/11/17	06:07 AM	SAMPLE 1	3710020-ADD-A	< 5	ug/L
W1165315	04/11/17	06:10 AM	SAMPLE 2	3710020-ADD-B	< 5	ug/L
W1165316	04/11/17	06:13 AM	SAMPLE 3	3710020-ADD-C	< 5	ug/L
W1165317	04/11/17	06:16 AM	SAMPLE 4	3710020-ADD-D	< 5	ug/L
W1165318	04/11/17	06:19 AM	SAMPLE 5	3710020-ADD-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    BLDG 200, kitchen, faucet at 2 compartment sink (171-01)
- SAMPLE 2    BLDG 200, exterior west wall, near lunch shelter, 3 fountains, lower left bubbler (171-02)
- SAMPLE 3    BLDG 400, exterior north wall, quadruple fountain, right bubbler (171-03)
- SAMPLE 4    BLDG 300, exterior west wall, adjacent to restrooms facing playground, triple fountain, right bubbler (171-04)
- SAMPLE 5    Restroom T-1, exterior north wall, triple fountain, right bubbler (171-05)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist