



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/28/17

San Diego Unified School District  
**Pershing Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167330	04/19/17	05:30 AM	SAMPLE 1	3710020-AGD-A	< 5	ug/L
W1167331	04/19/17	05:35 AM	SAMPLE 2	3710020-AGD-B	< 5	ug/L
W1167332	04/19/17	05:37 AM	SAMPLE 3	3710020-AGD-C	< 5	ug/L
W1167333	04/19/17	05:42 AM	SAMPLE 4	3710020-AGD-D	< 5	ug/L
W1167334	04/19/17	05:46 AM	SAMPLE 5	3710020-AGD-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Inside kitchen west wall across from kettles, 3 compartment sink, 2 faucets, left faucet
- SAMPLE 2      outside boys' gym across from lunch court near restroom, two single bubbler fountains, upper left fountain
- SAMPLE 3      Outside between 1004A -1002B classrooms, two single bubbler fountains, upper left fountain
- SAMPLE 4      outside near room 901, two single bubbler fountains, upper left fountain
- SAMPLE 5      outside near room 205, two single bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist