



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/26/17

San Diego Unified School District
Riley/New Dawn

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169370	05/17/17	06:14 AM	SAMPLE 1	3710020-BDH-A	< 5	ug/L
W1169371	05/17/17	06:10 AM	SAMPLE 2	3710020-BDH-B	< 5	ug/L
W1169372	05/17/17	06:18 AM	SAMPLE 3	3710020-BDH-C	< 5	ug/L
W1169373	05/17/17	06:22 AM	SAMPLE 4	3710020-BDH-D	< 5	ug/L
W1169374	05/17/17	06:28 AM	SAMPLE 5	3710020-BDH-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Administration bldg, Kitchen (south side of kitchen near storage room), faucet above 2 compartment sink
- SAMPLE 2 Administration building, Outside of auditorium facing lunch court (north), two single-bubbler fountains, upper right fountain
- SAMPLE 3 Kinder bldg, Exterior west wall outside room 17, triple bubbler fountain, middle bubbler
- SAMPLE 4 Classroom bldg C, Exterior wall northwest side outside room 16, triple bubbler fountain, left bubbler
- SAMPLE 5 New Dawn main office, Interior south wall of teacher workroom in admin portable, faucet at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist