



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 5/5/17

San Diego Unified School District
Ross Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168766	04/27/17	05:55 AM	SAMPLE 1	3710020-BCE-A	< 5	ug/L
W1168767	04/27/17	05:59 AM	SAMPLE 2	3710020-BCE-B	< 5	ug/L
W1168768	04/27/17	06:01 AM	SAMPLE 3	3710020-BCE-C	< 5	ug/L
W1168769	04/27/17	06:04 AM	SAMPLE 4	3710020-BCE-D	< 5	ug/L
W1168770	04/27/17	06:10 AM	SAMPLE 5	3710020-BCE-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kitchen south wall, spray faucet at single compartment sink
SAMPLE 2	Auditorium/cafeteria, north exterior wall, triple drinking fountain, right bubbler
SAMPLE 3	BLDG 1-6, exterior east wall, three single fountains, lowest left bubbler
SAMPLE 4	BLDG 7-12, exterior east wall, three single fountains, lowest left bubbler
SAMPLE 5	Admin/kindergarten bldg, exterior south wall, left lower bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist