



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
San Diego SCPA

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166155	04/13/17	06:00 AM	SAMPLE 1	3710020-AEB-A	< 5	ug/L
W1166156	04/13/17	06:04 AM	SAMPLE 2	3710020-AEB-B	< 5	ug/L
W1166157	04/13/17	06:08 AM	SAMPLE 3	3710020-AEB-C	< 5	ug/L
W1166158	04/13/17	06:12 AM	SAMPLE 4	3710020-AEB-D	< 5	ug/L
W1166159	04/13/17	06:15 AM	SAMPLE 5	3710020-AEB-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	BLDG 700 Cafeteria, in kitchen, north wall, single compartment sink faucet (368-01)
SAMPLE 2	BLDG 600 PE exterior north wall, triple fountain, right bubbler (368-02)
SAMPLE 3	BLDG 400, north of room 401, free standing concrete pedestal, single bubbler (368-03)
SAMPLE 4	BLDG 200, northwest wall, lower right bubbler (368-04)
SAMPLE 5	Admin bldg A, east of finance office, free standing concrete pedestal, single bubbler (368-05)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist