



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Serra High

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169348	04/29/17	06:13 AM	SAMPLE 1	3710020-BDC-A	< 5	ug/L
W1169349	04/29/17	06:17 AM	SAMPLE 2	3710020-BDC-B	< 5	ug/L
W1169350	04/29/17	06:19 AM	SAMPLE 3	3710020-BDC-C	< 5	ug/L
W1169351	04/29/17	06:24 AM	SAMPLE 4	3710020-BDC-D	< 5	ug/L
W1169352	04/29/17	06:28 AM	SAMPLE 5	3710020-BDC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Main Office/ Building 1, South end of office hallway between RRs, single bubbler fountain
- SAMPLE 2 Building 2, Near rooms 213 and RRs, single bubbler fountain
- SAMPLE 3 Building 3 or 300 building, Outside North end near room 301, right triple bubbler fountain, middle bubbler
- SAMPLE 4 Building 4 or 400 building, Inside hallway near room 411 next to RRs, two single-bubbler fountains, left fountain
- SAMPLE 5 inside Kitchen near lunch court, Located on kitchen island, faucet above single compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist