



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/26/17

San Diego Unified School District  
**Standley Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172877	05/18/17	06:18 AM	SAMPLE 1	3710020-BIH-A	< 5	ug/L
W1172878	05/18/17	06:15 AM	SAMPLE 2	3710020-BIH-B	< 5	ug/L
W1172879	05/18/17	06:21 AM	SAMPLE 3	3710020-BIH-C	< 5	ug/L
W1172880	05/18/17	06:24 AM	SAMPLE 4	3710020-BIH-D	< 5	ug/L
W1172881	05/18/17	06:10 AM	SAMPLE 5	3710020-BIH-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Admin Building, West facing wall near lunch patio area on outside bldg, triple bubbler fountain, middle bubbler
- SAMPLE 2    Kitchen/Supply Room Bldg, East facing wall near lunch and RRs, two single bubbler fountains, upper right fountain
- SAMPLE 3    600 Building, West Facing Wall near rooms 602 and 603, dual bubbler fountain, right bubbler
- SAMPLE 4    Media Center Building, East facing wall next to restrooms, two single bubbler fountains, upper right fountain
- SAMPLE 5    Kitchen/Cafeteria Building, inside kitchen, faucet above two compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist