



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Torrey Pines Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170296	05/19/17	06:06 AM	SAMPLE 1	3710020-BFJ-A	< 5	ug/L
W1170297	05/19/17	06:10 AM	SAMPLE 2	3710020-BFJ-B	< 5	ug/L
W1170298	05/19/17	06:13 AM	SAMPLE 3	3710020-BFJ-C	< 5	ug/L
W1170299	05/19/17	06:16 AM	SAMPLE 4	3710020-BFJ-D	< 5	ug/L
W1170300	05/19/17	06:03 AM	SAMPLE 5	3710020-BFJ-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria, Outside east wall next to double doors to cafeteria, two single-bubbler fountains, lower left fountain
- SAMPLE 2 Rm 1-6 building, Next to #3 and RRs around corner, triple bubbler fountain, left bubbler
- SAMPLE 3 Kinder Playground, Outside at wall next to RRs, two single-bubbler fountains, lower left fountain
- SAMPLE 4 Kindergarten, K-2 inside classroom, bubbler on right sink
- SAMPLE 5 Kitchen, faucet on two compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist