



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Twain Morse

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172914	05/19/17	05:55 AM	SAMPLE 1	3710020-BII-A	< 5	ug/L
W1172915	05/19/17	05:59 AM	SAMPLE 2	3710020-BII-B	< 5	ug/L
W1172916	05/19/17	05:59 AM	SAMPLE 3	3710020-BII-C	< 5	ug/L
W1172917	05/19/17	06:08 AM	SAMPLE 4	3710020-BII-D	< 5	ug/L
W1172918	05/19/17	06:11 AM	SAMPLE 5	3710020-BII-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Restroom Bungalow (south end of campus), Two triple bubbler fountains, right fountain, middle bubbler
- SAMPLE 2 Bungalow B10, inside, bubbler at sink
- SAMPLE 3 Bungalow B11, inside, bubbler at sink
- SAMPLE 4 Bungalow B8/Office, inside, bubbler at sink
- SAMPLE 5 Bungalow B7, inside, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist